

LaRose Surveys, P.C.
Test Pit Evaluation

Client: Sabourin

Project#: 18036

Date: June 26, 2018

Site Address: Spear Street, Charlotte

Project Description: Replacement system

Logged By: Kevin LaRose

Witnessed By: Brian Tremback

Topographical Description: sloping hillside

Slope: 5-10%

Vegetation: mix of lawn and brush

Weather: Sunny, 75

Method of Excavation: excavator

Excavating Company: Friend

Test Pit #	Horizon	Depth (inches)	Texture	Color	Consistency	Structure	Redoximorphic Features	Comments
101		0-6" 6-29" 29-48"	very fine sandy loam silty loam silty loam	dark brown brown brown	loose friable friable	granular subang blocky subang blocky	none none concentrations	
102		0-8" 8-18" 18-36'	very fine sandy loam fine sandy loam silty loam	dark brown brown brown	loose friable friable	granular subang blocky subang blocky	none none concentrations	
103		0-6" 6-20" 20-38"	very fine sandy loam fine sandy loam silty loam	dark brown brown brown	loose friable friable	granular subang blocky subang blocky	none none concentrations	

LaRose Surveys, P.C.
Test Pit Evaluation