



March 18, 2016

Mr. Joe Rheame, Zoning Admin.
Town of Charlotte Municipal Offices
P.O. Box 119, Charlotte, Vt. 05445,

Subject: WW-138-0705, Moore & Rushford, 692 Church Hill Road, Charlotte, Vt.

Dear Joe,

Per our client, Christine Rushforth, I have observed the new construction of the upgrade to the sanitary system serving the residence noted above.

Specifically:

The existing 750 gallon steel septic tank located in the cellar of the homestead has been pumped, filled with concrete, and abandoned in place under the floor.

The existing sanitary collector under the homestead has been rerouted with 4" Sch. 40 PVC piping to a sleeve in the foundation on the northwest corner of the house.

A new 4" PVC delivery line was installed along the west side of the home and connected to the existing 1000 gallon precast concrete septic tank located at the southwest corner of the homestead.

The disturbed soil has been properly stabilized by raking out the excavation and applying seed and mulch to the site.

Please add this letter to your file referenced above.

Thank you for your time in this process.


Regards, Andy

Andre Lambert Jr., Lic Designer 406 AB

Trudell Consulting Engineers, (TCE)

TRUDELL CONSULTING ENGINEERS (TCE)

Copies: Christine Rushford, Tara L. MacAskill, Esq.



TRUDELL CONSULTING ENGINEERS

478 BLAIR PARK ROAD, WILLISTON, VT 05495 | 802.879.6331 | WWW.TCEVT.COM