

**Hinsdale III Property  
Meadowside Drive  
Charlotte, Vermont  
Percolation Test Results**

**All tests were performed on October 28, 2016 at a depth of 18" - 24"**

PT-1	Drop Time (min)	Total Drop Time (min)	Total Drop (inches)	Drop Rate (min/inch)
	8.6	8.6	1	8.6
	11.9	20.5	2	10.3
	13.7	34.2	3	11.4
	14.9	49.1	4	12.3
	15.7	64.8	5	13.0
	16.4	81.2	6	13.5
	17.0	98.2	7	14.0
	---	<b>1440.0</b>	---	<b>23.0</b>

PT-2	Drop Time (min)	Total Drop Time (min)	Total Drop (inches)	Drop Rate (min/inch)
	9.4	9.4	1	9.4
	13.8	23.2	2	11.6
	16.6	39.7	3	13.2
	17.4	57.1	4	14.3
	18.7	75.8	5	15.2
	19.8	95.6	6	15.9
	20.7	116.3	7	16.6
	---	<b>1440.0</b>	---	<b>28.7</b>

\*NOTE:  
Drop time includes fill time for each of the seven runs.