

Hinsdale III Property
Meadowside Drive
Charlotte, Vermont
Percolation Test Results
All tests were performed on October 28, 2016 at a depth of 18" - 24"




Chart 1