

December 17, 2013

Jason & Jensa Bushey
648 Bingham Brook Rd.
Charlotte, VT 05445

RE: Bushey Property, 648 Bingham Brook Rd, Charlotte, VT, WW-138-1314 Inspection and Certification Letter.

Dear Jason & Jensa:


In an effort to fulfill State water and wastewater regulations, Town zoning regulations and ensure a clear title for your property, I've conducted the required inspections of the subject water and wastewater disposal systems. I offer the following required inspection and certification report which should be recorded in the Town land records.

In this regard, between September 3, 2013 and December 13, 2013, Spafford and Sons Water Wells, Brian Lyman Excavating, and Stephen Revell, Licensed Designer #178B properly sited, constructed and inspected the drilled bedrock well and water service connection to the house and the mound type wastewater disposal system for your 4 bedroom residence. All required inspections were conducted including the well and water service connection to the residence; building sewer, septic tank, pump station and force main placement; site preparation, sand approval and sand placement; seepage bed, pipe and stone placement; hydraulic testing with even 6' heads; fabric placement and mound covering; and final grading, seeding and mulching. In all regards, the subject water and wastewater disposal system were constructed in accordance with my design which was subsequently approved under WW-138-1314 by the Town of Charlotte on behalf of the State of Vermont. Based upon my inspections I am now in a position to certify that the subject water and wastewater disposal systems are operational (when the residence is completely constructed) and indicate to the Town of Charlotte that the property qualifies for a Certificate of Occupancy relative to them. In this regard, "I hereby certify the installation and related information submitted is true and correct and that in the exercise of my reasonable professional judgment, the approved water and wastewater disposal systems have been installed in accordance with the design and all design conditions, were inspected, were properly tested and successfully met those performance tests."


In closing, to ensure long life to the wastewater system, the septic tank should be pumped every three years and the effluent filter in the septic tank should be cleaned in the spring and fall. The access points for the septic tank and sump station are a grade and easily located.

If you have any questions, please give me a call.

Very truly yours,
Lincoln Applied Geology


Stephen Revell, CPG
Licensed Class B Designer #178

SR/h



RECEIVED
DEC 18 2013
CHARLOTTE
PLANNING & ZONING

Enclosure

CC: Thomas Mansfield, Sewage Control Officer, Town of Charlotte

F:\CLIENTS\2013\13087\Inspection and Certification Letter.docx