



July 15, 2009

Jean Guy and Connie Beliveau
1485 Church Hill Road
Charlotte, VT 05445

RE: The Believeau Property, Church Hill Road, Charlotte, VT
Replacement Wastewater Disposal System Inspection &
Certification Report (WW-138-0830)

Dear Jean Guy and Connie:

In an effort to fulfill State and Town water and wastewater regulations and ensure clear title for your property, I have conducted the required inspections of the subject replacement wastewater disposal system that was recently installed. I offer the following required inspection and certification report which should be recorded in the Town of Charlotte land records.


In this regard, between June 11, 2009 and July 14, 2009 R&J Trucking Company and Stephen Revell, CPG, Licensed Class B Designer #178, properly sited, constructed and inspected the replacement mound type disposal system for your property. All required inspections were conducted including: system stakeout; site preparation; sand sieve analysis approval; sand and distribution system placement; Step[®] tank and forcemain placement; pressure and hydraulic testing; curtain drain installation; and finish grading, seeding and mulching. The distribution system performed perfectly with three feet of head and less than five percent variation. Connection to the existing cast iron building sewer where it exits the basement was witnessed, as well as the removal of the former septic tank. In all regards, the replacement wastewater disposal system was constructed in complete accordance with my design which was subsequently approved by the Town of Charlotte on behalf of the State of Vermont under WW-138-0830. Based upon my inspections, I am now in the position to certify that the subject replacement disposal system is fully operational and indicated to the Town of Charlotte the property qualifies for certificate of occupancy relative to it. In this regard, "I hereby certify the installation related information submitted is true and correct and that the exercise of my reasonable professional judgment, the approved replacement wastewater disposal system has been installed in accordance with the design and all design conditions, was inspected, was properly tested and successfully met those performance tests."

To insure long life to the wastewater system the septic tank portion of the Step[®] tank should be pumped every three years and the filter surrounding the pump should be inspected and cleaned on at least a once a year basis. The access points for the Step[®] tank are at grade and easily located.


If you have any questions, please do not hesitate to contact me.

Very truly yours,

Lincoln Applied Geology, Inc.



Stephen Revell, CPG
Licensed Class B Designer



CC: Tom Mansfield, Town of Charlotte
SR/kj

F:\CLIENTS\2008\08092\July 15.doc Letter of Certification.doc



Lincoln Applied Geology, Inc.
Environmental Consultants