

July 20, 2016

Adam Hausmann
648 Bingham Brook Rd.
Charlotte, VT 05445

RE: Hausmann Property, 985 Bingham Brook Rd, Charlotte, VT, WW-138-1523 Inspection and Certification Letter.

Dear Adam:


In an effort to fulfill State water and wastewater regulations, Town zoning regulations and ensure a clear title for your property, I've conducted the required inspections of the new disposal system for the reconstructed residence and the connection of farm stand to it. I offer the following required inspection and certification report which you should record in the Town land records.


In this regard, between January 9, 2016 and July 15, 2016, Steve Denton Excavating, and Stephen Revell, Licensed Designer #178W properly sited, constructed and inspected the mound type wastewater disposal system for your 3 bedroom residence and the connection of the farm stand to it. All required inspections were conducted including the building sewers from the farm stand and residence; septic tank, pump station and force main placement; site preparation, sand approval and sand placement; seepage bed, pipe and stone placement; hydraulic testing with even 4' heads; fabric placement and mound covering; and final grading, seeding and mulching. The existing connection of the well to the farm stand and residence were also inspected. In all regards, the subject water and wastewater disposal system were constructed in accordance with my design which was subsequently approved under WW-138-1523 by the Town of Charlotte on behalf of the State of Vermont. Based upon my inspections, I am now in a position to certify that the subject water and wastewater disposal systems are operational and indicate to the Town of Charlotte that the property qualifies for a Certificate of Occupancy relative to them. In this regard, "I hereby certify the installation and related information submitted is true and correct and that in the exercise of my reasonable professional judgment, the approved water and wastewater disposal systems have been installed in accordance with the design and all design conditions, were inspected, were properly tested and successfully met those performance tests."

In closing, to ensure long life to the wastewater system, the septic tank should be pumped every three years and the effluent filter in the septic tank should be cleaned in the spring and fall. The access points for the septic tank and pump station are at grade and easily located.

If you have any questions, please give me a call.

Very truly yours,
Lincoln Applied Geology, Inc.


Stephen Revell, CPG
Licensed Designer #178BW



SR/mh

Enclosure

CC: Joseph Rheaume, Administrative Officer, Town of Charlotte
F:\CLIENTS\2015\15080\Inspection and Certification Letter.docx